

Crown Square, Galway

August, 2022



Phase 1

The Contract Cleaning team began by removing any large pieces of debris left over after two years of construction.



Underground Car Park

Preparation for the painting of the floor

The underground Car Park in Crown Plaza, Galway needed a deep clean in preparation for the painting of the floor.

The ground had to be completely free of any dust or debris to ensure a smooth application of the concrete sealant and paint.



Phase 2

To tackle the dirty and dusty environment, the team used the GSR1100 vacuum sweeper to effectively sweep the floor. The vacuum sweeper was effective at sweeping up the dust, that had gathered to 1-2cm in some places.

Phase 3

Once the dust and dirt was cleared from the underground car park, the floor needed a deep clean. The team used the GSDR802 scrubber dryer to clean the ground and used the GSD385 for smaller corners. The scrubber cleaned and dried the floor simultaneously allowing painting to start sooner rather than later.

For more case studies click [here](#)